




# SELDÉN




595-077  
2002-10-07


①



②



③



If a boom light is fitted, electrical cables are likely to be directly above the slider's track.

Drill very carefully to avoid any damage to the cables.