

Cable hose instruction

For deck stepped masts with cables running through cable hose assembly (319-620-01,-02 & 319-639-01).

All cables should be tied in a loop and secured by a cable tie at a distance "A" from the mast heel as shown below.

Stepping the mast:

- Before stepping, feed the cable loop into the mast. A piece of tape can be used to secure the cables to the heel to prevent the loop from falling out while the mast is raised.
- Gently feed the cables through the cable hose and into the boat while lowering the mast. Check that the cable hose goes through the heel into the mast without jamming. One person is needed below deck to pull the cables. Make sure the cables do not jam.

Mast section		A	HL
C156		250-300 mm	300 mm
C175	F176		
C193	F194		
C211	F212	300-350 mm	350 mm
C227	F228		
C245	F246		
C264	F265	300-350 mm	350 mm
C285	F286		
C304	F305		

Note! Cable hose assembly on in-mast furling masts:

On mast sections F176 and F194 the cable hose goes into the (aft) sail compartment. On all other F-masts the cable hose goes into the forward compartment.

